

Clean Gun Head

ACTIVITY NO.	ACTIVITY	TICK WHEN COMPLETED
Priority	Put on Respirator as specified for spray painting, Protective Clothing, Eye Protection, and PVC Gloves.	
1	Flush the gun with solvent.	
2	Wipe the face of the nozzle after flushing.	
3	Turn off the air ball valve at the air intake.	
4	Release the solvent flush tank pressure.	
5	Remove the nozzle and clean it.	
6	Remove the Mix Housing and clean it.	
7	Wipe the gun block face with a clean rag.	
8	Hang the gun with the gun block exit holes facing downwards.	

NOTE: Solvent flush of system should precede cleaning of gun, accumulator, etc. After disconnecting and cleaning catalyst system.

NOTE: When using solvent for cleaning or flushing, be sure to store the used solvent in a manufacturer-approved container with a tight-fitting lid for storage while waiting to run the used solvent through your recycling equipment. Solvents evaporate quickly.

WARNING: Solvents such as acetone are extremely flammable.

ACTIVITY NO.	ACTIVITY	TICK WHEN COMPLETED
9	Visually inspect the open ports of the gun block for signs of gelled material after flushing.	

ABNORMAL CONDITIONS OBSERVED AND CORRECTED

Abnormal Condition	✓ when corrected

OPERATORS NAME: _____ DATE: _____

SIGN OFF WHEN SHUTDOWN CHECKS ARE COMPLETED : _____